

Casaday

TABLE OF CONTENTS

LIST OF FIGURES 3

LIST OF TABLES 4

LIST OF PHOTOGRAPHS 5

LIST OF PRINCIPAL INVESTIGATORS 6

EXECUTIVE SUMMARY 7

1. INTRODUCTION 8

1.1. Authority 8

1.2. Review of Bank Erosion 9

1.3. Field Investigation 9

1.4. Geomorphic Analysis 9

1.5. Study Schedule 9

1.6. General Location 9

2. CHANNELS AFFECTING SACRAMENTO AND FEATHER RIVER EROSION 10

2.1. Lateral Bank Changes 10

2.2. Incision Channels 10

2.3. Channel Width 10

2.4. Channel Migration 10

3. GEOLOGY OF THE NORTHEASTERN PART OF THE SACRAMENTO AND FEATHER RIVER BASIN 10

3.1. General Geology 10

3.2. Topography of the Sacramento and Feather River Basins 10

3.3. Channels in the Sacramento and Feather River Basins 10

3.4. Summary 10

4. SEDIMENTOLOGY OF SACRAMENTO AND FEATHER RIVERS 10

4.1. Recent Sediments 10

4.2. Holocene Sediments 10

4.3. Grain Size Characteristics of Recent Sediments 10

**Geomorphic Analysis and Bank Protection
Alternatives Report
for
Sacramento River (RM 78-194) and
Feather River (RM 0-28)**

Prepared for

**U.S. Army Corps of Engineers
Sacramento District
Sacramento, California**

**Contract No. DACW05-88-D-0044
Delivery Order #5**

by

**Water Engineering & Technology, Inc.
419 Canyon Avenue, Suite 225
Fort Collins, Colorado 80525**

May 1990